MR IV 32...81

CONTENT

AR

Augmented Reality, often shortened to AR, is a technology that blends digital information into the real world. For more information, please click here or directly try yourself by scanning the QR code with your phone.

SCAN ME

**Supported by** (Android)

Supported by (Apple)

Please scan the QR code above and open on AR-enabled device.

There is a possibility that the configuration will fail. If that happens, please try a different product.

3D view

3D

HOW TO ACTIVATE 3D?

To activate the interactive 3D view in Acrobat Reader, you need to select, at the top of the page, **Options** and then
Trust this document

Zoom

Moves you toward or away from objects in the scene when you drag vertically. You can also zoom with the hand tool by holding down Shift as you drag.

Pan

Moves the model vertically and horizontally only. You can also pan with the hand tool: Ctrl-drag.

Rotate

Turns 3D objects around relative to the screen. How the objects move depends on the starting view, where you start dragging and the direction in which you drag.

CAD plugins

With our CAD integrations, you can use 3Dfindit directly in your CAD system and make your work easier with additional comfort functions, such as replacing a part and many more.


To the plugins

2D derivation

ISO view

Bill-Of-Materials

N°	Description	Amount
1	A_MR_IV_50_UO3A_63 B5_221_B3_____SM	1

Technical drawings

B3   B6   B7

B8   V5   V6

Technical data

GRANDEZZA (Gear reducer size / mm)	50
ESECUZIONE (Gear reducer design)	UO3A
MOTORTYPE (Motor size)	63 B5
I (Transmission ratio)	221
FC (Mounting position)	B3
AL (Standard / solid low speed shaft)	No
ALCM (Design for hollow low speed shaft)	No
FB5 (B5 flange)	No
FQ (Square flange)	No
RALC (Hollow low speed shaft washer / protection)	No
SFP (Shaft-mounting arrangements)	No
A18 (Motor type)	No motor
A19 (Motor size)	-
A20 (Terminal box position)	-
A21 (Power)	-
A22 (Poles)	-
A32 (Frequency)	-
A23 (Directive)	-
A24 (Efficiency)	-
A25 (Motor mounting position)	-
A26 (Second shaft end)	-
A27 (Cooling)	-
A28 (Encoder)	-
A29 (Drip proof cover)	-
A30 (Relese lever)	-
AA (/ mm)	50
A1 (/ mm)	40
A (/ mm)	86
B (/ mm)	75
C1 (/ mm)	70.5
D (Ø H7 / mm)	28
D1 (Ø / mm)	16
E1 (/ mm)	30
F ()	M6x12
G (/ mm)	98
H (h11 / mm)	100

H0 (h11 / mm)	67
H1 (h12 / mm)	49.0
K (Ø / mm)	9.5
L (/ mm)	13
L1 (/ mm)	12.0
M (Ø / mm)	100
N (Ø t8/h6 / mm)	85
P (Ø / mm)	120
Q (/ mm)	3.0
T (/ mm)	126
U (/ mm)	95
Z (/ mm)	53
P1 (Ø / mm)	140
X (Ø / mm)	122
Y (/ mm)	229
Y1 (/ mm)	394
W (/ mm)	101
W1 (/ mm)	191
MASS (Mass / kg)	16
OLIO (Oil quantity)	0.50

MR IV 32...81

E-Learning

Discover free training for 3Dfindit, the search engine for engineers, designers, and architects. Our 30 to 50-minute interactive courses provide you with comprehensive knowledge about the platform. Upon successful completion, you will receive a certificate. Start your first course now and master 3Dfindit!

Become an Expert of Digital Engineering

E-Learning

Get a free certificate!

Boost your career and get ready for Industry 4.0!

Learn more

Start course