

Pressure Switches, Series PM1

► Operating pressure: -0.9 - 16 bar ► mechanical ► electr. connection: Plug, ISO 4400, form A ► Spring-loaded bellow, adjustable



Measurement Relative pressure
Switching element microswitch (input/output)

Max. switching frequency1,5 HzProtection against overpressure80 barAmbient temperature min./max.-20 °C / +80 °CMedium temperature min./max.-10 °C / +80 °CMediumCompressed air hydraulic oil

Shock resistance max. 15 g (XYZ direction)

Vibration resistance 10 g (60 - 500 Hz) (XYZ direction)

Switching point adjustable

Hysteresis max. switching pressure difference

DC operating voltage min./max. 12 - 30

Operational voltage AC min./max. 12 V AC - 250 V AC

Mounting orientation Any

Mounting types via through holes

Function change-over contact (mechanical)

Protection class IP65
Weight 0.16 kg

Materials:

Housing Aluminum

Seals Acrylonitrile Butadiene Rubber

Electr. connection Brass, nickel-plated

Technical Remarks

- Switching function increasing pressure: contact switches from 1-2 to 1-3. Switching function decreasing pressure: contact switches from 1-3 to 1-2.
- Notice: Too-high currents can damage contacts. Inductive or capacitive loads must be equipped with appropriate spark-quenching!
- The microswitch has silver-plated contacts.


	Туре	Operating pres- sure range min./max.	Compressed air connection	Repeatability (% of full scale value)	Fig.	Note	Part No.
		[bar]					
I		-0.9 / 0				2)	R412010711
	PM1-M3-G014	-0.9 / 3	Internal thread, G 1/4	± 1 %	Fig. 1	3)	R412022752
						1); 3) I	R412010712
	PM1-M3-G014	0.2 / 16	Internal thread, G 1/4	± 1 %	Fig. 1	1); 2)	R412010713
	 PM1-M3-F001	-0.9 / 0	Flange with O-ring, Ø 5x1,5	± 1 %	Fig. 2	2)	R412010714
	PM1-M3-F001	0.2 / 16	Flange with O-ring, Ø 5x1,5	± 1 %		1); 3)	R412010715
					Fig. 2	1); 2)	R412010718

- 1) Min. switching pressure range 0.2 bar falling/0.5 bar rising
- 2) Scope of delivery: with electrical connector
- 3) Scope of delivery: without electrical connector

Sensor technologies ► Pressure sensors

Pressure Switches, Series PM1

► Operating pressure: -0.9 - 16 bar ► mechanical ► electr. connection: Plug, ISO 4400, form A ► Spring-loaded bellow, adjustable




- 1) Electrical connector
- 2) Adjustment screw, self-holding




Pressure Switches, Series PM1

► Operating pressure: -0.9 - 16 bar ► mechanical ► electr. connection: Plug, ISO 4400, form A ► Spring-loaded bellow, adjustable



- 1) Electrical connector
- 2) Adjustment screw, self-holding
 3) cylinder screw M5x30 (included in scope of delivery)
- 4) O-ring Ø5x1,5 (included)

PIN assignment for electrical connector



- 1) +UB
- 2) break contact
- 3) NO (make contact)
- 4) GND




Sensor technologies ► Pressure sensors

Pressure Switches, Series PM1

► Operating pressure: -0.9 - 16 bar ► mechanical ► electr. connection: Plug, ISO 4400, form A ► Spring-loaded bellow, adjustable

differential switching pressure characteristic curve (-0,9 – 0 bar)



A) p1 (-), min.

B) p1 (-), max.

p1 (+) = upper switching pressure with increasing pressure


p1 (-) = lower switching pressure with decreasing pressure



Pressure Switches, Series PM1

► Operating pressure: -0.9 - 16 bar ► mechanical ► electr. connection: Plug, ISO 4400, form A ► Spring-loaded bellow, adjustable

differential switching pressure characteristic curve (0,2 – 16 bar)



A) p1 (-), min.

B) p1 (-), max.

p1 (+) = upper switching pressure with increasing pressure

p1 (-) = lower switching pressure with decreasing pressure

 Δ p1 = max. operating pressure difference or hysteresis

Example:

p1 (+) = 8 bar > p1(-) = 7.6 bar

 Δ p1 = 0.4 bar

max. permissible continuous current I max. [A] with ohmic load

U [V]	30	48	60	125	250				
I [A] 1)	5	5	5	5	5				
I [A] 2)	3	1,2	0,8	0,4	_				

reference cycle: 30/min., reference temperature: +30 °C

1) AC

2) DC

max. permissible continuous current I max. [A] with inductive load

U [V]	30	48	60	125	250				
I [A] 1) 3)	3	3	3	3	3				
I [A] 2) 4)	2	0.55	0.4	0.15	_				

reference cycle: 30/min., reference temperature: $+30~^{\circ}\text{C}$

1) AC

2) DC

3) cos ≈ 0,7°

4) L/R ≈ 10 ms

Part numbers marked in bold are available from the central warehouse in Germany, see the shopping basket for more detailed information